



Capability & Price List

Engine Type : CF6-80C2

Airfoil Services Sdn Bhd
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi
Taman Sains Selangor 1
Kota Damansara PJU5
47810 Petaling Jaya
Selangor Darul Ehsan
Malaysia
Tel No: +6 03 61453600

Workscope	Repair No	Description	Additional Info	Repair Type
ATA Chapter: 72-57-01		LPT Blade Stage 1		
9373M31P04, 9373M31P05, 1536M21P02, 1536M21P01, 1536M21P03				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	001	Blend Airfoil	-	OEM
	002	Oxidation & Corrosion Removal	-	OEM
	003	Intermediate Oxidation & Corrosion Removal	-	OEM
	004	Heavy Oxidation & Corrosion Removal	-	OEM
	005	Blend Dovetail	-	OEM
	006	Pre-Twist	-	OEM
	010	Strip Aluminide Coating	-	OEM
Full Repair	001	Blend Airfoil	-	OEM
	002	Oxidation & Corrosion Removal	-	OEM
	003	Intermediate Oxidation & Corrosion Removal	-	OEM
	004	Heavy Oxidation & Corrosion Removal	-	OEM
	005	Blend Dovetail	-	OEM
	006	Pre-Twist	-	OEM
	007	CMF & Interlock & Seal Teeth Repair	-	OEM
	010	Strip Aluminide Coating	-	OEM
Extended Repair 1	008	Replace Aluminide Coating	-	OEM
ATA Chapter: 72-57-01		LPT Blade Stage 2		
9373M32P04, 9373M32P05, 1536M22P01, 1536M22P02, 1536M22P03				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	001	Blend Airfoil	-	OEM
	002	Oxidation & Corrosion Removal	-	OEM
	003	Intermediate Oxidation & Corrosion Removal	-	OEM
	004	Heavy Oxidation & Corrosion Removal	-	OEM
	005	Blend Dovetail	-	OEM
	006	Pre-Twist	-	OEM
	010	Strip Aluminide Coating	-	OEM
Full Repair	001	Blend Airfoil	-	OEM
	002	Oxidation & Corrosion Removal	-	OEM
	003	Intermediate Oxidation & Corrosion Removal	-	OEM
	004	Heavy Oxidation & Corrosion Removal	-	OEM
	005	Blend Dovetail	-	OEM
	006	Pre-Twist	-	OEM
	007	CMF & Interlock & Seal Teeth Repair	-	OEM
	010	Strip Aluminide Coating	-	OEM
Extended Repair 1	008	Replace Aluminide Coating	-	OEM



Capability & Price List

Engine Type : CF6-80C2

Airfoil Services Sdn Bhd
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi
Taman Sains Selangor 1
Kota Damansara PJU5
47810 Petaling Jaya
Selangor Darul Ehsan
Malaysia
Tel No: +6 03 61453600

Workscope	Repair No	Description	Additional Info	Repair Type
<u>ATA Chapter: 72-57-01</u>		<u>LPT Blade Stage 3</u>		
9373M33P03, 9373M33P05, 9373M33P06, 9373M33P07, 9373M33P08, 9373M33P09, 9373M33P04				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	001	Blend Airfoil	-	OEM
	002	Oxidation & Corrosion Removal	-	OEM
	003	Intermediate Oxidation & Corrosion Removal	-	OEM
	004	Heavy Oxidation & Corrosion Removal	-	OEM
	005	Blend Dovetail	-	OEM
	006	Pre-Twist	-	OEM
	010	Strip Aluminide Coating	-	OEM
Full Repair	001	Blend Airfoil	-	OEM
	002	Oxidation & Corrosion Removal	-	OEM
	003	Intermediate Oxidation & Corrosion Removal	-	OEM
	004	Heavy Oxidation & Corrosion Removal	-	OEM
	005	Blend Dovetail	-	OEM
	006	Pre-Twist	-	OEM
	007	CMF & Interlock & Seal Teeth Repair	-	OEM
	010	Strip Aluminide Coating	-	OEM
Extended Repair 1	008	Replace Aluminide Coating	-	OEM
Extended Repair 2	SB 72-0843	Eddy Current Inspection Stage 3		OEM
<u>ATA Chapter: 72-57-01</u>		<u>LPT Blade Stage 4</u>		
9373M34P03, 9373M34P04, 9373M34P05, 9373M34P05_FAI				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	001	Blend Airfoil	-	OEM
	002	Oxidation & Corrosion Removal	-	OEM
	003	Intermediate Oxidation & Corrosion Removal	-	OEM
	004	Heavy Oxidation & Corrosion Removal	-	OEM
	005	Blend Dovetail	-	OEM
	006	Pre-Twist	-	OEM
	007	CMF & Interlock & Seal Teeth Repair	-	OEM
Full Repair	001	Blend Airfoil	-	OEM
	002	Oxidation & Corrosion Removal	-	OEM
	003	Intermediate Oxidation & Corrosion Removal	-	OEM
	004	Heavy Oxidation & Corrosion Removal	-	OEM
	005	Blend Dovetail	-	OEM
	006	Pre-Twist	-	OEM
	007	CMF & Interlock & Seal Teeth Repair	-	OEM
Extended Repair 1	013	Replace Chromide Coating	-	OEM
Extended Repair 2	SB 72-1446	Stage 4 CMF Modification	-	OEM



Capability & Price List

Engine Type : CF6-80C2

Airfoil Services Sdn Bhd
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi
Taman Sains Selangor 1
Kota Damansara PJU5
47810 Petaling Jaya
Selangor Darul Ehsan
Malaysia
Tel No: +6 03 61453600

Workscope	Repair No	Description	Additional Info	Repair Type
<u>ATA Chapter: 72-57-01</u>		<u>LPT Blade Stage 5</u>		
9373M35P03, 9373M35P04				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	001	Blend Airfoil	-	OEM
	002	Oxidation & Corrosion Removal	-	OEM
	003	Intermediate Oxidation & Corrosion Removal	-	OEM
	004	Heavy Oxidation & Corrosion Removal	-	OEM
	005	Blend Dovetail	-	OEM
	006	Pre-Twist	-	OEM
Full Repair	001	Blend Airfoil	-	OEM
	002	Oxidation & Corrosion Removal	-	OEM
	003	Intermediate Oxidation & Corrosion Removal	-	OEM
	004	Heavy Oxidation & Corrosion Removal	-	OEM
	005	Blend Dovetail	-	OEM
	006	Pre-Twist	-	OEM
	007	CMF & Interlock & Seal Teeth Repair	-	OEM
Extended Repair 1	013	Replace Chromide Coating	-	OEM